

110 Large Fab - Steps - 2 - B4B	4 pcs	0.00 13.79	QC 5 - 82	
			Large Fab - 1 - B4B	
			Large Fab - 10 - B4B	
			Large Fab - 2 - B4B	
			Large Fab - 3 - B4B	
			Large Fab - 4 - B4B	
			Large Fab - 5 - B4B	
			Large Fab - 6 - B4B	
			Large Fab - 7 - B4B	CC Dec, 4, 2020
			Large Fab - 8 - B4B	
			Large Fab - 9 - B4B	
			Large Fab - 11 - B4B (Various)	
			Large Fab - 12 - B4B	
120 QC 9	4 pcs	0.00 0.00	QC 9 - 10	
			QC 9 - 18 DAS	
			QC 9 - 24 24	DEC 07 2020
			QC 9 - 43 9-89	
			QC 9 - 50	
			QC 9 - 9	
130 QC 5	4 pcs	0.00 0.00	QC 5 - 10	
			QC 5 - 12	
			QC 5 - 17	
			QC 5 - 18	
			QC 5 - 19	
			QC 5 - 22 DAS	
			QC 5 - 24 24	DEC 07 2020
			QC 5 - 3 9-89	
			QC 5 - 43	
			QC 5 - 49	
			QC 5 - 51	
			QC 5 - 58	
			QC 5 - 68	
			QC 5 - 9	
			QC 5 - 50	
			QC 5 - 30	
			QC 5 - 40	
			QC 5 - 61	
			QC 5 - 81	
			QC 5 - 82	
140 Handfinish - 1-1 Chemical-B4B	4 pcs	0.00 1.65	Handfinish - 1 - 1 - B4B	BEB 08/12/2020
			Handfinish - 1 - 2 - B4B	
			Handfinish - 1 - 3 - B4B	
			Handfinish - 1 - 4 - B4B	
			Handfinish - 1 - 5 - B4B	
			Handfinish - 1 - 6 - B4B	
			Handfinish - 1 - 7 - B4B	
			Handfinish - 1 - 8 - B4B	
			Handfinish - 1 - 9 - B4B	
			Handfinish - 1 - 10 - B4B	
			Handfinish - 1 - 11 - B4B	
			Handfinish - 1 - 12 - B4B	
			Handfinish - 1 - 13 - B4B	
			Handfinish - 1 - 14 - B4B	
			Handfinish - 1 - 15 - B4B	
			Handfinish - 1 - 16 - B4B	
			Handfinish - 1 - 17 - B4B	
			Handfinish - 1 - 18 - B4B	
			Handfinish - 1 - 19 - B4B	

			Handfinish - 1 - 20 - B4B	
			Handfinish - 1 - 21 - B4B	
			Handfinish - 1 - 22 - B4B	
150 QC 7	4 pcs	0.00 0.00	QC 7 - 10	
			QC 7 - 13	
			QC 7 - 14	
			QC 7 - 15	
			QC 7 - 17	
			QC 7 - 18	
			QC 7 - 19	
			QC 7 - 2	
			QC 7 - 28	
			QC 7 - 3	
			QC 7 - 30	
			QC 7 - 34	
			QC 7 - 36	
			QC 7 - 37	
			QC 7 - 41	
			QC 7 - 47	
			QC 7 - 48	
			QC 7 - 51	
			QC 7 - 58	
			QC 7 - 59	
			QC 7 - 60	
			QC 7 - 9	
			QC 7 - 68	
			QC 7 - 50	
			QC 7 - 67	
			QC 7 - 40	
			QC 7 - 24	
			QC 7 - 43	
			QC 7 - 61	
			QC 7 - 81	
			QC 7 - 76	
			QC 7 - 79	
			QC 7 - 83	
			QC 7 - 82	
			QC 7 - 87	
160 Large Fab - Steps - 3 - B4B	4 pcs	0.00 5.75	Large Fab - 1 - B4B	
			Large Fab - 10 - B4B	
			Large Fab - 2 - B4B	
			Large Fab - 3 - B4B	
			Large Fab - 4 - B4B	
			Large Fab - 5 - B4B	
			Large Fab - 6 - B4B	
			Large Fab - 7 - B4B	
			Large Fab - 8 - B4B	
			Large Fab - 9 - B4B	
			Large Fab - 11 - B4B (Various)	
			Large Fab - 12 - B4B	
170 QC 10	4 pcs	0.00 0.00	QC 10 - 10	
			QC 10 - 18	
			QC 10 - 24	
			QC 10 - 43	
			QC 10 - 50	
			QC 10 - 58	
			QC 10 - 9	
			QC 10 - 68	

180 QC 5	4 pcs	0.00 0.00	QC 10 - 81	
			QC 5 - 10	
			QC 5 - 12	
			QC 5 - 17	
			QC 5 - 18	
			QC 5 - 19	
			QC 5 - 22	
			QC 5 - 24	
			QC 5 - 3	
			QC 5 - 43	
			QC 5 - 49	DEC 09 2020
			QC 5 - 51	DAS 81 9-89
			QC 5 - 58	
			QC 5 - 68	
			QC 5 - 9	
			QC 5 - 50	
			QC 5 - 30	
			QC 5 - 40	
			QC 5 - 61	
			QC 5 - 81	
			QC 5 - 82	
185 Handfinish - 2-1 Pressure-B4B	4 pcs	0.00 1.65	Handfinish - 2 - 1 - B4B	3 FEB 09/12/2020
			Handfinish - 2 - 2 - B4B	
			Handfinish - 2 - 3 - B4B	
			Handfinish - 2 - 4 - B4B	
190 Powdercoat - 1 White Gl(A)-B4B <i>m 254/469.</i> <i>START: 11:00.</i> <i>OV.T: 300°</i> <i>FINISH: 11:30.</i>	4 pcs	0.00 0.70	Powdercoat - 1 - B4B	
			Powdercoat - 2 - B4B	
			Powdercoat - 3 - B4B	20-12-10. 28 08
			Powdercoat - 4 - B4B	
			Powdercoat - 5 - B4B	
			Powdercoat - 6 - B4B	
			Powdercoat - 7 - B4B	
			Powdercoat - 8 - B4B	
			Powdercoat - 9 - B4B	
			Powdercoat - 10 - B4B	
200 QC 3	4 pcs	0.00 0.00	QC 3 - 10	
			QC 3 - 13	
			QC 3 - 15	M 20-12-11
			QC 3 - 17	
			QC 3 - 18	
			QC 3 - 2	
			QC 3 - 28	
			QC 3 - 3	
			QC 3 - 30	
			QC 3 - 34	
			QC 3 - 36	
			QC 3 - 41	
			QC 3 - 51	
			QC 3 - 58	
			QC 3 - 59	
			QC 3 - 68	
			QC 3 - 9	
			QC 3 - 40	
			QC 3 - 19	
			QC 3 - 43	
			QC 3 - 24	
			QC 3 - 61	
			QC 3 - 81	
			QC 3 - 82	

			QC 3 - 87	
			QC 3 - 47	
210 Handfinish - 3-1 - WingWalk-B4B	4 pcs	0.00 1.65	Handfinish - 3 - 1 - B4B	Jul 20 12 11
			Handfinish - 3 - 2 - B4B	
			Handfinish - 3 - 3 - B4B	
			Handfinish - 3 - 4 - B4B	
			Handfinish - 3 - 5 - B4B	
220 QC 5	4 pcs	0.00 0.00	QC 5 - 10	
			QC 5 - 12	
			QC 5 - 17	
			QC 5 - 18	
			QC 5 - 19	
			QC 5 - 22	
			QC 5 - 24	
			QC 5 - 3	
			QC 5 - 43	
			QC 5 - 49	
			QC 5 - 51	
			QC 5 - 58	
			QC 5 - 68	
			QC 5 - 9	
			QC 5 - 50	
			QC 5 - 30	
			QC 5 - 40	DEC 14 2020
			QC 5 - 61	
			QC 5 - 81	
			QC 5 - 82	
230 Packaging 3-1 - Stock - B4B	4 pcs	0.00 0.00	Packaging 3 - 1 - B4B	
			Packaging 3 - 2 - B4B	
			Packaging 3 - 3 - B4B	
			Packaging 3 - 4 - B4B	
			Packaging 3 - 5 - B4B	DAS 69 9-89
			Packaging 3 - 6 - B4B	
			Packaging 3 - 7 - B4B	
			Packaging 3 - 8 - B4B	
			Packaging 3 - 9 - B4B	
			Packaging 3 - 10 - B4B	
			Packaging 3 - 11 - B4B	DEC 14 2020
			Packaging 3 - 12 - B4B	
			Packaging 3 - 13 - B4B	
			Packaging 3 - 14 - B4B	
			Packaging 3 - 15 - B4B	
			Packaging 3 - 16 - B4B	
			Packaging 3 - 17 - B4B	
			Packaging 3 - 18 - B4B	
			Packaging 3 - 19 - B4B	
			Packaging 3 - 20 - B4B	
			Packaging 3 - 21 - B4B	
			Packaging 3 - 22 - B4B	
			Packaging 3 - 23 - B4B	
			Packaging 3 - 24 - B4B	
			Packaging 3 - 25 - B4B	
			Packaging 3 - 26 - B4B	
			Packaging 3 - 27 - B4B	
			Packaging 3 - 28 - B4B	
			Packaging 3 - 29 - B4B	
			Packaging 3 - 30 - B4B	
			Packaging 3 - 31 - B4B	
			Packaging 3 - 32 - B4B	

Plex 11/12/20 11:55 AM Dart.lajeunesse.marie

240 QC 21 - SA	4 pcs	0.00 0.00	Packaging 3 - 33 - B4B	
			Packaging 3 - 34 - B4B	
			Packaging 3 - 35 - B4B	
			Packaging 3 - 36 - B4B	
			Packaging 3 - 37 - B4B	
			QC 21 - SA - 21	
			QC 21 - SA - 70	DEC 14 2020
			QC 21 - SA - 9	DAS 2 21
			QC 21 - SA - 77	9-8 9-89
			QC 21 - SA - 28	

Part Op 100 - (Fabricate per Dwg) 1-Cut D2842-1 using D2622 extrusion as per Dwg D2842 2-Drill D2842-1 using Jig DT8272 as Descriptions: per Dwg D2842 ***DO NOT OPEN HOLES*** 3-Debur and bevel ends for welding

105 - QC5- Inspect part completeness to step on W/O

110 - (Weld per dwg A/R Aluminum rod Batch: _____) 1-Weld one end cap and (2) lugs using DT10058 as per Dwg D2842 2- OPEN HOLES TO SIZE AS PER DWG (0.250") 3-Grind end cap weld flush

120 - (QC9- Inspect visual per QSI004- Fusion Welds)

130 - (QC5- Inspect part completeness to step on W/O)

140 - (Chemical Conversion Coat per QSI005 4.1)

150 - (QC7-Inspect Chemical Conversion Coat)

160 - (Weld per dwg A/R Aluminum rod Batch: _____) 1-Remove alodine prior to welding. Weld end cap as per Dwg D2842. 2-Grind end cap weld flush.

170 - (QC10- Inspect visual per QSI004- ground welds)

180 - (QC5- Inspect part completeness to step on W/O)

185 - (Pressure Wash per QSI005 4.3/ Clean and remove all markings) ***Touch up step with alodine per qsi 005 prior to powder coat***

190 - (White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum) START TIME: _____

200 - (QC3- Inspect Part Finish)

210 - (Wing Walk as per dwg QSI005 4.4 Batch _____) 1-Install inserts as per Dwg D2842 2-Wing Walk as per Dwg D2842 and QSI 005 4.1 Batch: _____

220 - (QC5- Inspect part completeness to step on W/O)

230 - (Identify as per dwg & Stock Location: _____)

240 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2622-120C	Step Extrusion	4 pcs (1 ea)	100-Large Fab - Steps - 1	5269726
D2734	Step End Plate	8 pcs (2 ea)	100-Large Fab - Steps - 1	5241255
D3459-1	Float Step Mounting Plate	8 pcs (2 ea)	100-Large Fab - Steps - 1	5241255
D3459-3	Float Step Mounting Plate	8 pcs (2 ea)	100-Large Fab - Steps - 1	5241312
MS27039C1-07	Screw	12 Ea (3 ea)	210-Handfinish - 3-1- WingWalk-B4B	52417846
NAS1149C0332R	Washer (AN960C10L)	12 Ea (3 ea)	210-Handfinish - 3-1- WingWalk-B4B	5304795
NAS1329C3KB130	Insert	12 Ea (3 ea)	210-Handfinish - 3-1- WingWalk-B4B	5023261
NAS1515H3L	Washer	12 Ea (3 ea)	210-Handfinish - 3-1- WingWalk-B4B	5297591

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Steps - 1	D2622-120C	4	139	0
	D2734	8	109	0
	D3459-1	8	14	0
	D3459-3	8	19	0
	MS27039C1-07	12	29	0
210-Handfinish - 3-1- WingWalk-B4B	NAS1149C0332R	12	3,012	0
	NAS1329C3KB130	12	36	0
	NAS1515H3L	12	124	0

Part Specifications

Specifications could not be found.